ASSEMBLY INSTRUCTIONS

ITEM NO: B2100-K-HB/B2100-KQ-HBLEG ITEM NO: B2100-Q-HB/B2100-KQ-HBLEG

(BOX 1) BOX OF HEADBOARD

ITEM	DRAWING	DESCRIPTION	QTY
A		HEADBOARD	1
В	[HEADBOARD INNER LEG SUPPORT	2
C		HEADBOARD LEG SUPPORT	2

(BOX 2) BOX OF HEADBOARD LEG


ITEM	DRAWING	DESCRIPTION	QTY
D	HO)	HEADBOARD LEG - RIGHT	1
E	H	HEADBOARD LEG - LEFT	1

(BOX 1) HARDWARE LIST

ITEM	DRAWING	DESCRIPTION	QTY
1		SHORT ALLEN KEY (M4)	1
2		CONNECTION BOLT (M6 x 40mm) W/SPRING WASHER & WASHER MEDIUM	4
3		CONNECTION BOLT (M6 x 40mm) W/SPRING WASHER, WASHER MEDIUM, & WASHER LARGE	12



 $\frac{COMPLETED\ HEADBOARD}{ASSEMBLY}$



THE HARDWARE IS LOCATED IN THE PACKING ITEMS.

NOTE : MUST TIGHTEN THE BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION

(BOX 1)

BOX OF FOOTBOARD

BOX OF FOOTBOARD				
ITEM	DRAWING	DESCRIPTION	QTY	
A		FOOTBOARD	1	
В	٥	BUN FOOT	2	
C		WOODEN SLAT	4	
D	Û	WOODEN SUPPORT WITH ADJUSTER	4	

(BOX 2) BOX OF SIDE RAIL

BOA OF SIDE RAILE			
ITEM	DRAWING	DESCRIPTION	QTY
E		SIDE RAIL	2

(BOX 1) HARDWARE LIST


DRAWING	D DO OD IDDIO II	
210111110	DESCRIPTION	QTY
	ALLEN KEY (M4)	1
	ALLEN KEY (M5)	1
	CONNECTION BOLT (M8 x 30mm) W/SPRING WASHER & WASHER MEDIUM	8
	CONNECTION BOLT (M6 x 40mm)	4
(3) minimus	CSK SCREW (M4 x 32mm)	8
	SCREW DRIVER (*)	1
		ALLEN KEY (M5) CONNECTION BOLT (M8 x 30mm) W/SPRING WASHER & WASHER MEDIUM CONNECTION BOLT (M6 x 40mm) CSK SCREW (M4 x 32mm)




(*) The Manufacturer does not provide item 6.

STEP 1

Please refer ITEM NO: B2100-K-HB / B2100-KQ-HBLEG ITEM NO: B2100-Q-HB / B2100-KQ-HBLEG




STEP 2



THE HARDWARE IS LOCATED IN THE PACKING ITEMS.

NOTE : MUST TIGHTEN BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION



THE HARDWARE IS LOCATED IN THE PACKING ITEMS.

NOTE : MUST TIGHTEN BOLTS & SCREWS PERIODICALLY. WITH USE BOLTS & SCREWS MAY BECOME LOOSE. CHECK TIGHNESS OF ALL BOLTS & SCREWS EVERY 6-8 WEEKS.

CLEANING INSTRUCTION