










ASSEMBLY INSTRUCTIONS INSTRUCCIONES





2211T-4072 TABLE 2211T-4072 MESA

PARTS LIST LISTA DE PARTES

1		1PC / PIEZA
2		4PCS / PIEZAS
3		2PCS / PIEZAS
4		1PC / PIEZA
5		2PCS / PIEZAS
6		2PCS / PIEZAS

A		Ø5/16" x 18 x 1-1/2"	22PCS / PIEZAS
B		M4x45mm	4PCS / PIEZAS
C		M4 x58mm	1PC / PIEZA

ASSEMBLY INSTRUCTIONS INSTRUCCIONES



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.