

Part # BS-PRIDE XX

20-0319


PARTS



A



B



C



D



E



x4 (M6)

F




x4 (M6x30mm)

G




H


1




REMOVE
BLACK CAP
AND THROW
AWAY



2



3



4



SIT TO SECURE



Do not over tighten.
 Do not use power tools to assemble.