









# ASSEMBLY INSTRUCTIONS INSTRUCCIONES




2212T-48 TABLE  
2212T-48 MESA

## PARTS LIST LISTA DE PARTES

1		1PC / PIEZA
2		4PCS / PIEZAS
3		1PC / PIEZA
4		1PC / PIEZA

A	 Ø5/16" x 18 x 2-3/4"	8PCS / PIEZAS
B	 Ø5/16" x 18 x 1-1/2"	1PC / PIEZA
C	 M4x45mm	4PCS / PIEZAS
D	 M4 x58mmT	1PC / PIEZA

## ASSEMBLY INSTRUCTIONS INSTRUCCIONES



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.  
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.