


ASSEMBLY INSTRUCTION



Finish:



Step 2:



Hardware List:

No.:	Description	Drawing	Size	Q' ty
Α	Short Bolt		Ø5/16" X2-1/2 "	5
В	Long Bolt		Ø5/16" X3-1/2 "	2
С	Lock Washer	©	Ø5/16" X12mm	7
D	Flat Washer	0	Ø5/16" X22mm	7
E	wood tenon		Φ 5mm	1