


3 Parts: Hanging Chair, Support Frame and Base

You will find the hardware packed inside the base

- (1)  Bolt x 2 (2)  Nut x 2 (3)  Spring x 1 (4)  Spring attachment x 1 (5)  Spanner x 1

Step 1 : Take out the hardware package from the base tube. Insert the support frame to the base. Ensure that both holes are aligned and put in the bolt (1) and attach the nut tightly (2).

Step 2 : Install the spring (3) by inserting it into the attachment (4).



Maximum weight: 120 kg