

Assembly Instructions

B677W-315 ANDOVER 5/0 Q HEADBOARD, FOOTBOARD & SLATS-WHITE B677W-335 ANDOVER 5/ 0-6 /6 Q/EK SIDE RAILS-WHITE B677W-415 ANDOVER 4/6 F HEADBOARD, FOOTBOARD & SLATS-WHITE B677W-535 ANDOVER 3/ 3-4 /6 T/F SIDE RAILS-WHITE

B677B-315 ANDOVER 5/0 Q HEADBOARD, FOOTBOARD & SLATS-NUTMEG B677B-335 ANDOVER 5/0-6 /6 Q/EK SIDE RAILS-NUTMEG B677B-415 ANDOVER 4/6 F HEADBOARD, FOOTBOARD & SLATS-NUTMEG


B677B-535 ANDOVER 3/3-4/6 T/F SIDE RAILS-NUTMEG

Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items and compare with the parts list and/or hardware list shown below. STEP 1

and of hardware list shown below				
PARTS LIST				
ITEM	DRAWING	DESCRIPTION	QTY	
1	B	HEAD BOARD	1 PC	
2	A	FOOT BOARD	1 PC	
3		HB LEG POST (L)	1 PC	
4		HB LEG POST (R)	1 PC	
5		SIDE RAILS	2 PCS	
6		SLATS SUPPORT	4 PCS	
7		WOODEN SLAT	4 PCS	

HARDWARD LIST				
ITEM	DRAWING	DESCRIPTION	QTY	
A	0	JCBB (M8) 8 x 35MM (NYLOK)	4 PCS	
В	0	Spring Washer M8 x22mm	4 PCS	
C	0	Flat Washer M8 x 16 x 1.6mm	4 PCS	
D		ALLEN KEY M5 5 x 35 x120MM	1 PC	
Е	Comming	C.S.K SCREW (M4) 4 x32mm	8 PCS	

Screw Driver is not included



Step 1: Attach and tighten the leg posts (3 & 4) to the head board (1) by inserting JCBB bolt (A) with washers (B & C).

PAGE 1 OF 2 MADE IN MALAYSIA

NOTE:MUST TIGHTEN SCREW PERIODICALLY.WITH USE SCREWS WILL BECOME LOOSE CHECK THIGHT OF ALL SREWS EVERY 6-8 WEEKS





Assembly Instructions

B677W-315 ANDOVER 5/0 Q HEADBOARD, FOOTBOARD & SLATS-WHITE B677W-335 ANDOVER 5/ 0-6 /6 Q/EK SIDE RAILS-WHITE B677W-415 ANDOVER 4/6 F HEADBOARD, FOOTBOARD & SLATS-WHITE B677W-535 ANDOVER 3/ 3-4 /6 T/F SIDE RAILS-WHITE

B677B-315 ANDOVER 5/0 Q HEADBOARD, FOOTBOARD & SLATS-NUTMEG B677B-335 ANDOVER 5/0-6 /6 Q/EK SIDE RAILS-NUTMEG B677B-415 ANDOVER 4/6 F HEADBOARD, FOOTBOARD & SLATS-NUTMEG

B677B-535 ANDOVER 3/3-4/6 T/F SIDE RAILS-NUTMEG





NOTE:MUST TIGHTEN SCREW PERIODICALLY.WITH USE SCREWS WILL BECOME LOOSE CHECK THIGHT OF ALL SREWS EVERY 6-8 WEEKS.

MADE IN MALAYSIA