Progressive®


ASSEMBLY INSTRUCTION

Item No: 1724

Description: CORNER SOFA

IMPORTANT NOTE:

- Place all parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- Check to be sure that you have all parts and hardware.
- Remove all wrapping materials, including staples & packing straps before you start to assemble
- Do not tighten all screws/bolts until all completely assembled.
- Keep all hardware parts out of reach of children.



1724	NO TO	TOTAL PA	ART	QTY	1724	NO	тот	AL PART
1724	NO	DESCRIP	TION	QII	1724	NO	DESCRIPTION	
	Α		Bench Back	2 PCS		1		JCBC Bolts M16X 15
	В		Right Bench	1 PC		2		JCBC Bolts M16x20
	С		Left Bench	1 PC				JCBC Bolts
	D		Corner Bench	1 PC		3		M16x50
	E		Table Top	1 PC		4		Flat Washer M6x16
			Leg	16		5		Flat Washer M6x19
	F		Leg	PCS		6		Spring Washer M6x13MM
	G		Support	2 PCS				INIOX I SIVIIVI
	Н		Magic Tape	2 PCS		7		Allen Key
	I		Bench Back Cushion	4 PCS		8		Socket Head Bolts M6x15
	J		Corner Bench Back Cushion	2 PCS				
	К		Bench Cushion	2 PCS				
	L		Corner Bench Cushion	1 PC				

QTY

68

PCS

6 PCS

6 PCS

74

PCS

6 PCS

80

PCS

6 PCS

6 PCS




IMPORTANT NOTE:

- Place all parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- Check to be sure that you have all parts and hardware.
- Remove all wrapping materials, including staples & packing
- Do not tighten all screws/bolts until all completely assembled.
- Keep all hardware parts out of reach of children.

Right Bench (A) -

L724-	PART LIST				L724		PART LIST			
LBRB	NO	DESCRIPT	TON	QTY		NO	DESCRIPTION		QTY	
	А		Bench Back	1 PC		1		JCBC Bolt M6x15	18 PCS	
						2		JCBC Bolt M6x20	3 PCS	
	В		Right bench	1 PC		3		JCBC Bolt M6x50	3 PCS	
	F		Bench Leg	4 PCS		4		Flat Washer M6x16	21 PCS	
							5		Flat Washer M6x19	3 PCS
	G		Leg Support	1 PC		6		Spring Washer M6x13	24 PCS	
	I		Bench Back Cushion	2 PCS		7		Allen key	2 PCS	
	K		Bench Cushion	1 PC						
						8		Socket Head Bolt	3 PCS	

MADE IN VIETNAM






IMPORTANT NOTE:

- Place all parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- Check to be sure that you have all parts and hardware.
- Remove all wrapping materials, including staples & packing
- Do not tighten all screws/bolts until all completely assembled.
- Keep all hardware parts out of reach of children.

-Left Bench(B) -

L724-		PART L	IST			PART LIST			
LBRB	NO	DESCRIPTION QTY		QTY	L724	NO	DESCRIPTION		QTY
	A		Bench Back	1 PC		1		JCBC Bolt M6x15	18 PCS
			Back			2		JCBC Bolt M6x20	3 PCS
	С		Left bench	1 PC		3		JCBC Bolt M6x50	3 PCS
	F		Leg	4 PCS		4		Flat Washer M6x16	21 PCS
			Leg Support 1 PC			5		Flat Washer M6x19	3 PCS
	G				6		Spring Washer M6x13	24 PCS	
	I		Bench Back Cushion	2 PCS		7		Allen key	2 PCS
	K		Bench Cushion	1 PC					
						8		Socket Head Bolt	3 PCS






Corner Bench (C) -

IMPORTANT NOTE:

- Place all parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- Check to be sure that you have all parts and hardware.
- Remove all wrapping materials, including staples & packing
- Do not tighten all screws/bolts until all completely assembled.
- Keep all hardware parts out of reach of children.

1.704	PART LIST					
L724	NO	DESCR	QTY			
	1	JCBC Bolt M6x15		16 PCS		
	4		Flat Washer M6x16	16 PCS		
	6		Spring Washer M6x13	16 PCS		
	7		Allen Key	1 PC		

L724-	PART LIST					
CRTB	NO	DESCRIPTION	QTY			
	D		Corner Bench	1 PC		
	F		Leg	4 PCS		
	Н		Magic tape	4 PCS		
	J		Corner Bench Back Cushion	2 PCS		
	L		Corner Bench Cushion	1 PC		





IMPORTANT NOTE:


- Place all parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- Check to be sure that you have all parts and hardware.
- Remove all wrapping materials, including staples & packing
- Do not tighten all screws/bolts until all completely assembled.
- Keep all hardware parts out of reach of children.


Table

L724-	PART LIST					
CRTB	NO	DESCRIPT	DESCRIPTION			
	Е		Table top	1 PC		
	F		Leg	4 PCS		

1.704	PART LIST					
L724	NO	DESCR	QTY			
	1		JCBC Bolt M6x15	16 PCS		
	4		Flat Washer M6x16	16 PCS		
	6		Spring Washer M6x13	16 PCS		
	7		Allen Key	1 PC		

STEP 1:





MADE IN VIETNAM